
Smoke and Dye Testing Summary

High Level Sewershed

Run Summary ————————————————————————————————————								
Test ID	Test Type	Date Inspected	Company / Super.	Blower MH	Ground Condition	Notification Made?	Total Length	
S1028-113	Smoke	10/16/2008	ADS/TM	S11GG_036MH	Dry	Yes	1,972.06	



Smoke and Dye Testing Summary

High Level Sewershed

Run Summary —								
Test ID	Test Type	Date Inspected	Company / Super.	Blower MH	Ground Condition	Notification Made?	Total Length	
S1028-113	Smoke	10/16/2008	ADS/TM	S11GG_036MH	Dry	Yes	1,972.06	

Isolated Pipes

	S13GG_008MH	239.7000	
1400 0041411			8
11GG_021MH	S11GG_040MH	149.5144	8
11GG_030MH	S11GG_018MH	57.28034	8
11GG_041MH	S11GG_034MH	71.77873	8
11GG_040MH	S11GG_030MH	108.0564	8
11GG_018MH	S13GG_025MH	229.6896	8
11GG_011MH	S11GG_002MH	169.2625	8
11GG_036MH	S11GG_030MH	260.7546	8
11GG_034MH	S11GG_044MH	131.707	8
11GG_044MH	S11GG_021MH	43.46798	8
11GG_002MH	S11GG_034MH	95.26768	8
11GG_037MH	S11GG_011MH	289.0229	8
11GG_045MH	S11GG_037MH	126.5530	8
1 1 1	1GG_041MH 1GG_040MH 1GG_018MH 1GG_011MH 1GG_036MH 1GG_034MH 1GG_044MH 1GG_002MH	1GG_041MH S11GG_034MH 1GG_040MH S11GG_030MH 1GG_018MH S13GG_025MH 1GG_011MH S11GG_002MH 1GG_036MH S11GG_030MH 1GG_034MH S11GG_034MH 1GG_044MH S11GG_021MH 1GG_002MH S11GG_034MH 1GG_0037MH S11GG_011MH	1GG_041MH \$11GG_034MH 71.77873 1GG_040MH \$11GG_030MH 108.0564 1GG_018MH \$13GG_025MH 229.6896 1GG_011MH \$11GG_002MH 169.2625 1GG_036MH \$11GG_030MH 260.7546 1GG_034MH \$11GG_044MH 131.707 1GG_044MH \$11GG_021MH 43.46798 1GG_002MH \$11GG_034MH 95.26768 1GG_037MH \$11GG_011MH 289.0229

Observations & Photos

Obs_ID S1028-113-OB01 Address 3015 Presbury St

Status Private Source Cleanout

Location Yard - front Nearest MH S11GG_036MH

Smoke from cleanout in front yard. 3015 Comments

Presbury St.



Picture \S1028-113-OB01-P01.jpg

Comments 3015 Presbury St. facing

Bloomingdale Rd.

Obs_ID S1028-113-OB02 Address 1707 Bloomingdale Rd

Status Private

Source

Location Yard - back Nearest MH S11II_004MH

Cleanout

Smoke from cleanout in back yard. 1707 Comments

Bloomingdale Rd.



Picture \S1028-113-OB02-P01.jpg

Comments Back of house, 1707

Bloomingdale Rd.



Wednesday, March 25, 2009

Page 2 of 3

Smoke and Dye Testing Summary

High Level Sewershed

Run Summary —								
Test ID	Test Type	Date Inspected	Company / Super.	Blower MH	Ground Condition	Notification Made?	Total Length	
S1028-113	Smoke	10/16/2008	ADS/TM	S11GG_036MH	Dry	Yes	1,972.06	

Obs ID S1028-113-OB03

Address Presbury St & Longwood St

Status Public
Source Catch Basin
Location Curb

Nearest MH S11GG_030MH

Comments Smoke from catch basin along curb on SW

corner of Presbury St & Longwood St



Picture \S1028-113-OB03-P01.jpg

Comments Presbury St & Longwood St

looking northeast

Obs_ID S1028-113-OB05

Address Bloomingdale Rd & Grayson St

Status Private
Source Catch Basin
Location Curb

Nearest MH S11GG_021MH

Comments Smoke from catch basin along curb on NW corner of Bloomingdale Rd & Grayson St.

Picture \S1028-113-OB05-P01.jpg

Comments Bloomingdale Rd & Grayson St

looking southeast

Obs_ID S1028-113-OB04 **Address** 3000 Grayson St

Status Private

Source Service Lateral

Location Paved concrete **Nearest MH** S11GG_044MH

Comments Smoke from service lateral under stairs behind

house. 3000 Grayson St.



Picture \S1028-113-OB04-P01.jpg

Comments Back of house, 3000 Grayson St.

Obs_ID S1028-113-OB06 **Address** 1603 Bloomingdale Rd

Status Public
Source Area Drain
Location Curb

Nearest MH S11GG_021MH

Comments Smoke from area drain along curb at 1603

Bloomingdale Rd.



Picture \S1028-113-OB06-P01.jpg

Comments Front of house, 1603

Bloomingdale Rd.

